



# Mahindra & Mahindra Ltd.

(Farm Equipment Sector, NetFlows360 Division, Phase IV, Industrial Area, S.A.S Nagar, Punjab-16055.)

PLOT NO , 28 ,  
GANDHINAGAR - .  
Mobile No. - 7590050650

GSTIN -

## Warranty Claims

W / CINo. : 1024260006  
TaxInvoiceNo. : NA  
NewTaxInvoiceNo(Partial Rejected Claims) :  
Dealer Name : KHUSHBU AUTO AGENCY  
Type of failure : Regular  
W / CL Date : 10/05/2025  
TaxInvoiceDate : NA  
NewTaxInvoiceDate :  
AO Name : N/A  
DealerCode : KAA382024

Sr. No. : MBNZMEBFEGGH00077  
Invoice Date : 26/03/2025  
Customer Name : MSDhoni  
AWDD Date : 10/05/2025  
Operation at the time of failure : Cultivator  
Dt. Of Complaint : 10/05/2025  
Customer Phone No : 7590060509  
Customer's complaint : CLUTCH RELEASE BEARING JAM  
Dealer's observation : CLUTCH FREE PLAY NIL  
Action Taken / Special Comments : Done  
EngineSrNo : GGH6BAA0163  
Invoice No : 7270712070  
Model : Commercial EV  
Hours : 100  
Job Card No : KAA38/26/05/A/J9  
Dt. of Repairs : 10/05/2025

## Labour

Sr. No.	Labour Code	Description	Lab Amt(Rs.)	Defect Code	Make Code
1	SLC111	1R & R Hose Radiator Outlet	12.98	ABD	SUE
2	LMICO	MICO PARTSCHARGES	1879.74	AAK	SSS

## LR Details

LR NO	Transporter's Name	Receipt Date	LR Date	No of cases	Claim Status
				0	Pending for Approval

## Pending for Approval Details

Pending for Approval By	Pending for Approval Name	Pending for Approval Remarks	Pending for Approval Date
NA	NA		NA